



Maintenance measures are being reported using dashboards rather than reports — the data is available in real time!




We have a better idea of what we're managing using TAMS with easy access to information!

Condition, Defects, Detailed	Checklists	🖬 Maintenance Management > Asset Performance > Noise Wall inspections 🏠 🗈 Save 🗘 Rela			Reload						
		Inspection Header A	tions ¥							:=	2
		* MnDOT Wall Number	Status	L.	Priority	Inspection Date	Side	Post Rating		Panel	-
Labels Count of TB_DEFICT_200	TRUMPERT PROMINES TO	N-007-191-65	Comple +	1		8/10/2011	Roade +				*
urk grazzier Fran 3° in Front of terminal Robate in bezated within 20°415° recorvers, area in digit ar non-traversakie within End 50° 4405-1414 di		N 010 231 01	Compl •	1	•	6/15/2011	Both •	1 - Good		1 - Goo	d v
nducaray han fearer (schen, struct, posit) allower ground line (C or more post net per namefastaren (s.g. kaper sole, post saksing, effent) hate is koastef older. 2013/1920 essevers, anna 6-digid pr kon travensakte withink find 501 1002 188 48		N-010-232-04	Comple •	1		6/16/2011	Both •	1 - Good		1 - Good	•
h grouter than 37 in know of terminal ana is located within 201475 receivers, area is digit or non-traversable within Kina 301 Undgit more than 21 where standard UND 481-48		N-010-232-24	Comple •	14	•	6/16/2011	Both •	1 - Good	٠	1 - Good	•
North Stand Standinger (Johns, structs, panks) allower ground lines 6° or more Velde some than 1° above standard M		N-010-232-74	Comple +	12		6/13/2011	Both •	1-Good		1 - Good	
	-	N-010-233-29	Comple -	12		6/13/2011	Back •	1-Good		1 - Good	•
		N-010-233-43	Comple +	1		6/15/2011	Roadu +	1 - Good	٠	1 - Good	•
nc) Mill Bruckure Condition III	-	N-010-234-20	Cample •	100	•	6/9/2011	Both •	2 - Fair	٠	2 - Fair	٠
4 - Showin 2 - Para 2 - Rain 3 - Rain 6 - Galandia Himpant Ma mountion	- Allina	< < < 2 of 440	iotal rows > >								>
Na Ingestion Pipe Condition @		-		·							
1 - Parro - Farro - J. Jar More - L. Jar More - Audot Insurant	- / /	Inspection Defects A MnDOT Wall Number	cions w Sides Insp	uul	Element	Element Material	Drimany D	efect Type		:=	
ameriai					1	-	-				
ofinical Assets	N-010-231-01	Roadway	•	Batten							
ing .		N-010-231-01	Roadway	•	Batten	• Wood •	Batten-to-Panel Connection				
Lighting Systems 🖅		N-010-231-01	Roadway		Panel	- Wood -	Vehicular D	amage			



Maintenance work planning is simplified with spatial analysis!



Maintenance and capital planning activities are better integrated.



Scoping activities are simplified with access to images, condition information, and checklists.

Section Signal Systems ITS Device Lighting Systems Pipe ITS Structure Miscellaneous Systems RWIS Grand Total	52 20 5 3 2 2 1 2438	DISTRICT 4 DISTRICT 6 DISTRICT 7 DISTRICT 8 ESS METRO MAINTENANCE RTMC	\$453,251,38 \$569,046,9 \$4667,748,25 \$62,024,32 \$1,230,692,56 \$4,690,885,07 \$97,394,45
Signal Systems ITS Device Lighting Systems Pipe ITS Structure Miscellaneous Systems	52 20	DISTRICT 6 DISTRICT 7 DISTRICT 8 ESS	\$569,046.9(\$469,748.25 \$62,024.32 \$1,230,692.58
Signal Systems ITS Device Lighting Systems Pipe ITS Structure	52 20	DISTRICT 6 DISTRICT 7 DISTRICT 8	\$569,046.90 \$469,748.25 \$62,024.32
Signal Systems ITS Device Lighting Systems Pipe	52 20	DISTRICT 6 DISTRICT 7	\$569,046.96 \$469,748.25
Signal Systems ITS Device Lighting Systems	52 20	DISTRICT 6	\$569,046.96
Signal Systems	52		
		DISTRICT 4	\$453,251.38
Section	105		
C +	105	DISTRICT 3	\$898,585.49
Lighting Units	139	DISTRICT 2	\$35,406.20
Termini	270	DISTRICT 1	\$604,017.60
Supports	613	District 💌	Total Dollars Billed
Linear Barriers	1226		·
Number of DR Claims by Asset Category for Calendar Year 2020 Asset Category		\$1,500,000.00 \$500,000.00 \$500,000.00 \$5.00	Construction of the construction of the state

TAMS work orders for damage restitution have reduced resource requirements and redundancies while increasing transparency and accuracy. In FY20, revenue from restitutions was \$4M. In just the first quarter of FY21, revenue from restitutions jumped to \$6M!